

29 Oct 2024

RE: CDR 24.2.383 Software Patch 1

**Bosch Automotive Service
Solutions Inc.**

Plymouth, Michigan USA

www.BoschCDRTool.com

Dear CDR Tool User,

A new patch for CDR software version 24.2 (CDR v24.2patch 1) is available from the Bosch CDR Website. Download the file *CDR24.2.383Setup_Patch1.zip*, unzip and run the *CDR24.2.383Setup_Patch1.exe* file unzipped into the folder. Below is included in the release of this patch.

Added support for the following vehicles:

BMW (all supported markets)

- 2024 2 Series Active Tourer
- 2024 5 Series
- 2024 7 Series
- 2024 i5
- 2024 i7
- 2024 iX
- 2024 X5
- 2024 X6
- 2024 X7
- 2024 XM
- 2025 1 Series
- 2025 2 Series Active Tourer
- 2025 2 Series Gran Coupe
- 2025 5 Series
- 2025 7 Series
- 2025 i5
- 2025 i7
- 2025 iX
- 2025 X3
- 2025 X5
- 2025 X6 CDR500 + Cable ID 860
- 2025 X7 CDR500 + Cable ID 860

- 2025 XM

MINI 2024~ 2025 (all supported markets)

- Aceman
- Convertible
- Countryman
- Hardtop

Oshkosh 2025 (US market)

- NGDV

Rolls-Royce 2024~2025 (all supported markets)

- Spectre

Addressed the following issues in 24.2patch 1:

- Legacy CDR, error opening a BMW CDR file from an ACSM6, after the file was saved by the user
- Legacy CDR, VW60, Pre-Crash time column reporting "0.0" sec across all the table.
- Legacy CDR, VWG vehicles, do not display EDIDs 441 and 442 in the CDR report for EDID list v0005 and v0008
- Legacy CDR, VW60 is not reading F187 from the ECU for OBD and D2M
- Legacy CDR, BMW i4 (ACSM6), cannot save a CDR file after being downloaded, CDR displays Error Line: 706 Disk Error -- Error number: 6 Overflow
- Ford RC8C, Events are not recorded 24.2
- BMW, when downloading ACM6 ECUs, error "Software ID is not supported: BMW 13"
- BMW, the VIN sequence number is not being masked after download/exported
- VW Group VW60, Incorrect Data Limitations
- 2025 Ford Bronco VIN Support
- 2025 BMW X5 ACM Not Supported
- 2024 Mazda MAZDA3 and CX30 for Japan market, Remove TVV Data Element
- GM FCM B (Sys Ref 1003): Additional Controller ID
- VW Group VW60, Record x (Invalid, Unknown EDID)
- GM ASCM (sys ref #1013), add new controller IDs
- GM Legacy, Korea and Japan markets, CSV export, addressed error "Error Number 5"
- 2024 Ford F-150 XLT This vehicle is not supported message

To download this new patch, please visit our website or by clicking on the link below for CDR24.2.383Setup_Patch1.zip.

Link: <https://cdr.boschdiagnostics.com/cdr/cdr-v242-system-software>

Software Release

CDR24.2.383Setup_Patch1.zip

Note: You MUST have CDR v24.2 installed prior to installing this patch.

IMPORTANT: You do not need a new activation certificate for 24.2 to use this patch release.

Please contact our technical support team if you require assistance:

Phone (US/Canada only): 1-855-BOSCH-TECH (1-855-267-2483)

Email: techsupport.diagnostics@us.bosch.com

Thank you,

The Bosch CDR Team
Bosch Automotive Service Solutions Inc.